

Printing Guidelines

DESK TOP LASER & COPIER



All PCL™ and Office Label materials are suitable for laser or copier printing. Please see the Printing Information Table for materials suitable for Ink Jet.

For best printing results:

For all materials:

Set the media type to: HEAVY or ULTRA HEAVY (media option in the print dialogue box).

Most PCL and Office materials can be printed from the standard paper trays (depending on the printer type - some will only allow Heavy Media settings when used from the by-pass tray).

Always fan the sheets well, taking care not to over bend and 'lift' the corners of any labels, discarding any that appear damaged.

For polyester grades it is useful to stack the feed tray sheet by sheet in order to introduce a layer of air between the sheets (this reduces the static).

Beware Polyester grades retain heat - sheets should be allowed to cool before removing from the exit tray.

Print small batches of polyester sheets, in order not to build up too much heat in the printer and increase the static.

Handy Tip

If colour laser printing DO NOT then overprint by Mono laser as the higher fusing temperature is likely to soften and smudge the original colour print.